



	Ref.	Rect2
Emiss.	1.0	1.0
Avg		38.4 °C
Min		23.8 °C
Max	29.4 °C	65.9 °C
Delta		36.5 °C

Equipment	Top of A ϕ Fuse
Location	6 FCE Substation: Feed to APC Fan
Condition	Overheating
Causes	Loose, dirty, or corroded connection.
Load	Unknown
Temperature Rise	36.5°C
Repair Priority Level	Level 4: Major discrepancy; repair immediately.
Action Suggested	Inspect, clean, and tighten connection.
Repairs Completed By:	

Repairs Completed On: _____

Date: 10/16/2005 Thermographer: J. Devi Thorp