



	Ref.	Rect2
Emiss.	1.0	1.0
Avg		42.7 °C
Min		23.7 °C
Max	45.5 °C	62.5 °C
Delta		17.0 °C

Equipment	Bφ on bottom of isolation contactor
Location	D.T. South Plant
Condition	Overheating
Causes	Loose, dirty, or corroded connection.
Load	Unknown
Temperature Rise	17.0 °C
Repair Priority Level	Level 4: Major discrepancy; repair immediately.
Action Suggested	Inspect, clean, and tighten connection.
Repairs Completed By:	

Repairs Completed On: \_\_\_\_\_

Date: 5/05/2005 Thermographer: J. Devi Thorp